

CIL
EMU CRITICAL ITEMS LIST

Page: 1
Date: 11/15/95

12/24/91 SUPERSEDES 01/02/90

ANALYST:

NAME	P/N	QTY	CRIT	FAILURE MODE & CAUSES	FAILURE EFFECT	RATIONALE FOR ACCEPTANCE
SECONDARY OXYGEN PACK CHECKOUT FIXTURE RELIEF VALVE, ITEM 495	2/2			495FM01: External gas leakage.	END ITEM: SOP or primary oxygen leakage to ambient.	A. Design - This item has a 140 micron filter at the inlet to limit contamination to the valve seat and seal. The seal is a low durometer elastomer (Fluoro Silicon) to provide maximum seat compression. The valve lower housing has stroke limit stops to prevent excessive elastomer creep. In addition, the elastomer is checked for hardness to assure adequate seal force. The interface seal is a radial type silicone rubber "O" seal. This seal is also made of elastomeric material which allows conformance of the seal to the housings being sealed and provides a sealing force over the tolerance and environmental ranges of the item.
8V799099-00 (1)				CAUSE: Damaged or missing housing seals or neck ring seal.	GPE INTERFACE: Excessive consumption of the emergency oxygen supply during the SOP regulator checkout or excessive consumption of primary O2 during fan checkout/and water dump.	B. Test - PDA: A leakage test is performed during SENU-60-018 in which the vent loop is pressurized with oxygen to 4.3 +/- 0.1 psig. Leakage is not to exceed 114 sec/min O2. Certification: The SCOF is certified to meet all requirements except shock testing based on analysis, acceptance testing of the first production unit and similar equipment experience with the Item 146 positive pressure relief valve. C. Inspection - O-ring grooves are 100% inspected per drawing dimensions and surface requirements. The Interface "O" ring is visually inspected. A cleanliness level of HS150 EH150B is maintained during assembly and testing of the checkout fixture relief valve. The SOP Checkout fixture is visually inspected at EOP and Final Inspection. EM1050 Cleanliness, EOP, and Final Inspection requires inspection points.

D. Failure History -
Related failures:

CEL
EMU CRITICAL ITEMS (16)

Page: 2
Date: 12/03/91

12/24/91 SUPERSEDES 01/02/90

ANALYST:

NAME	FAILURE	MODE & CAUSES	FAILURE EFFECT	RATIONALE FOR ACCEPTANCE
P/N	CRIT			
QTY				
	2/2	493FR011		<p>The SCBF Relief Valve is identical to the Item 146 Positive Pressure Relief Valve.</p> <p>J-EMU-146-AB02, J-EMU-146-AB03 and J-EMU-146-AB04 were written against the old design 146 aluminum valve, 5V767705, for creep of the elastomeric seat.</p> <p>This problem was addressed during the redesign to the stainless steel valve, 5V757936. Included in the redesign were the addition of steps to prevent compression/creep of the elastomeric seat.</p> <p>Other redesign features include the relocation of the flow orifice to isolate it from the valve seat/seat area. Three other RDR's J-EMU-146-A007(1/11/86), J-EMU-146-A008(9/10/86), and J-EMU-146-006(1/17/86); leakage at recent were caused by contamination of the valve seat caused by migration of corrosion products from the PLS0 structure (all three RDR's involve PLS0 101t only).</p>

E. Ground Turnaround -
Tested per PEMU-R-001; Preflight Leakage test.

F. Operational Use -
 CREW RESPONSE:
 Pre EVA (SOP CHECK): If detected during EVA prep (sop check), trouble-shoot problem. If no success, consider EMU 3 if available. EMU no go for EVA.
 Training:
 Standard EMU training covers this failure mode.
 Operational Considerations -
 Flight rules define go/no go criteria related to operational SOP. EVA checklist and EMU procedures verify hardware integrity and system operational status prior to EVA.

5EMU-44-001H
Page 1725
H1001